

Microsemi Corporation

June 21, 2019

Customer Notification No: CN19011

Subject

RTG4 LSRAM Circuit for Pipelined ECC and I/O Driven High at the End of Programming

Summary

This document describes two customer advisory notifications (CANs) for all RTG4 devices. The following table summarizes each CAN and the action required by the customer.

Notification	Description	Action Required
CAN 19011.1	LSRAM BLK Select De-assertion Circuit for Pipelined ECC	Regenerate the RAM with Libero SoC v11.9 SP3 (and later 11.x releases) or v12.1 (and later 12.x releases)
CAN 19011.2	I/O Driven High at the End of Programming	Regenerate the bitstream with Libero SoC v11.9 SP4 (and later 11.x releases) or v12.1 (and later 12.x releases)

CAN 19011.1 LSRAM BLK Select De-assertion Circuit for Pipelined ECC

Description of Change

An internal hold time issue can be observed on the LSRAM when the BLK select input is de-asserted after issuing a read command in pipelined-ECC mode. When the BLK select input de-asserts, it is supposed to clear the LSRAM data output latch, and eventually result in all-zero data sent to the LSRAM DOUT ports, depending on the number of pipeline stages enabled in the LSRAM. However, due to an internal hold time issue, the BLK select de-assertion clears the LSRAM data output latch so quickly that it violates the ECC pipeline register's hold time before it can capture the valid read data corresponding to the previously issued RAM read.

The RTG4 two-port and dual-port LSRAM configurators in Libero SoC v11.9 SP3 (and later 11.x releases) or v12.1 (and later 12.x releases) have been updated to generate an additional fabric-based circuit for pipelined-ECC mode. The additional circuit avoids the hold time issue by delaying BLK select de-assertion to the active LSRAM block. The mitigation circuit will be described in a future update to the RTG4 Fabric User's Guide (UG0574).

Note that along with this LSRAM configurator update, single-depth dual-port LSRAM components using pipelined-ECC mode that expose the BLK select input will no longer hold the most recent read data after de-asserting REN. The fabric-based mitigation circuit gates-off the read data output by the pipelined BLK select input, and thus the LSRAM read data output port will transition from the previous read data to all-zero on subsequent clock cycles, based on the number of pipeline stages enabled.

Application Impact

This issue only impacts RTG4 two-port and dual-port LSRAM in pipelined-ECC mode. This issue does not impact the following LSRAM configurations:

- Synplify-inferred LSRAM (Synplify does not infer pipelined-ECC mode.)
- Any configuration where the BLK select inputs are tied high
- Non-pipelined-ECC mode (with or without DOUT pipeline)
- Non-ECC mode (with or without DOUT pipeline)
- Two-port LSRAM configurator component without depth-cascading
- Dual-port LSRAM configurator component without depth cascading, and without exposing BLK select input on any port used for reading

- LSRAM port used exclusively for writes (There is no issue if BLK select input is de-asserted on that port after a write command is issued.)

This issue does not impact RTG4 uSRAM.

Action Required

To insert the mitigation circuit, existing designs must update to Libero SoC v11.9 SP3 (and later 11.x releases) or v12.1 (and later 12.x releases) and regenerate all LSRAM components using pipelined-ECC mode.

The software configurator update only applies to pipelined-ECC LSRAM components generated from the Libero IP catalog. Manually instantiated LSRAM instances can be replaced with LSRAM configurator components in the Libero SoC versions specified above to automatically insert the mitigation logic.

- Existing designs opened in the Libero SoC versions specified above will be invalidated if they contain any pipelined-ECC LSRAM component, and the user will be asked to regenerate the affected LSRAMs.
- Compile will generate an error if pipelined-ECC LSRAM catalog components still require regeneration.
- Static Timing Analysis (STA) must be rerun to check whether the updated LSRAM component with the additional circuit still meets timing requirements.

CAN 19011.2 I/O Driven High at the End of Programming

Description of Change

At the end of the RTG4 device programming cycle, outputs could be driven high momentarily before driving out the logic value specified by the design. Designs that have set the “output state during programming” in the boundary scan register (BSR) to ‘0’ and expect the output to remain low before, during, and after programming will see a brief high glitch at the end of programming. The glitch occurs after the JTAG test reset is issued at the end of programming when the output state control is handed-off from BSR control to fabric control and the fabric design starts operating. The glitch duration is design dependent because it depends on the propagation delay from the input pin to the output pin through the user fabric design. The worst case amplitude of the glitch is VDDI level of the I/O.

Libero SoC v11.9 SP4 (and later 11.x releases) or v12.1 (and later 12.x releases) contains a fix to the bitstream generation tool that prevents this glitch by adding a JTAG instruction before issuing the JTAG reset at the end of programming. This JTAG instruction releases the input state from BSR control to fabric control before the outputs are released from BSR control. This provides additional time for the input PAD logic levels to propagate into the fabric design and set the initial output values before the output state control is handed over to the fabric logic.

Application Impact

Evaluate if you have critical outputs that must remain low before, during, and after programming to maintain desired system functionality. If so, then the design bitstream must be regenerated to eliminate this output glitch at the end of programming. There is no reliability impact to the device because the I/O is driven high for a short time.

Action Required

If you are concerned about this glitch, regenerate the bitstream using Libero SoC v11.9 SP4 (and later 11.x releases) or v12.1 (and later 12.x releases).

Contact Information

If you have further questions about this subject, contact Microsemi Technical Support department by using the support portal at <https://soc.microsemi.com/Portal/Default.aspx>

Regards,

Microsemi Corporation

Customer Notice (CN) or Customer Advisory Notice (CAN) are confidential and proprietary information of Microsemi and is intended only for distribution by Microsemi to its customers, for customers' use only. It must not be copied or provided to any third party without Microsemi's prior written consent.

Affected Part Numbers

Microsemi Part Number	DLA SMD Number
RT4G150-CB1657PROTO	
RT4G150-CG1657B	5962-1620801QXF
RT4G150-CG1657E	5962-1620805QXF
RT4G150-CG1657EV	
RT4G150-CG1657V	5962-1620809VXF
RT4G150-CG1657PROTO	
RT4G150-CQ352B	
RT4G150-CQ352E	
RT4G150-CQ352EV	
RT4G150-CQ352PROTO	
RT4G150-LG1657B	5962-1620803QZC
RT4G150-LG1657E	5962-1620807QZC
RT4G150-LG1657EV	
RT4G150-LG1657V	5962-1620811VZC
RT4G150-LG1657PROTO	
RT4G150-1CB1657PROTO	
RT4G150-1CG1657B	5962-1620802QXF
RT4G150-1CG1657E	5962-1620806QXF
RT4G150-1CG1657EV	
RT4G150-1CG1657V	5962-1620810VXF
RT4G150-1CG1657PROTO	
RT4G150-1CQ352B	
RT4G150-1CQ352E	
RT4G150-1CQ352EV	
RT4G150-1CQ352PROTO	
RT4G150-1LG1657B	5962-1620804QZC
RT4G150-1LG1657E	5962-1620808QZC
RT4G150-1LG1657EV	
RT4G150-1LG1657V	5962-1620812VZC
RT4G150-1LG1657PROTO	
RT4G150L-CG1657EV	
RT4G150L-LG1657EV	
RT4G150L-CQ352EV	
RT4G150L-CG1657E	
RT4G150L-LG1657E	
RT4G150L-CQ352E	

Microsemi Part Number	DLA SMD Number
RT4G150L-CG1657B	
RT4G150L-LG1657B	
RT4G150L-CQ352B	
RT4G150L-CG1657PROTO	
RT4G150L-CB1657PROTO	
RT4G150L-LG1657PROTO	
RT4G150L-CQ352PROTO	

**Microsemi Headquarters**

One Enterprise, Aliso Viejo,
CA 92656 USA
Within the USA: +1 (800) 713-4113
Outside the USA: +1 (949) 380-6100
Sales: +1 (949) 380-6136
Fax: +1 (949) 215-4996
Email: sales.support@microsemi.com
www.microsemi.com

© 2019 Microsemi. All rights reserved. Microsemi and the Microsemi logo are trademarks of Microsemi Corporation. All other trademarks and service marks are the property of their respective owners.

Microsemi makes no warranty, representation, or guarantee regarding the information contained herein or the suitability of its products and services for any particular purpose, nor does Microsemi assume any liability whatsoever arising out of the application or use of any product or circuit. The products sold hereunder and any other products sold by Microsemi have been subject to limited testing and should not be used in conjunction with mission-critical equipment or applications. Any performance specifications are believed to be reliable but are not verified, and Buyer must conduct and complete all performance and other testing of the products, alone and together with, or installed in, any end-products. Buyer shall not rely on any data and performance specifications or parameters provided by Microsemi. It is the Buyer's responsibility to independently determine suitability of any products and to test and verify the same. The information provided by Microsemi hereunder is provided "as is, where is" and with all faults, and the entire risk associated with such information is entirely with the Buyer. Microsemi does not grant, explicitly or implicitly, to any party any patent rights, licenses, or any other IP rights, whether with regard to such information itself or anything described by such information. Information provided in this document is proprietary to Microsemi, and Microsemi reserves the right to make any changes to the information in this document or to any products and services at any time without notice.

Microsemi, a wholly owned subsidiary of Microchip Technology Inc. (Nasdaq: MCHP), offers a comprehensive portfolio of semiconductor and system solutions for aerospace & defense, communications, data center and industrial markets. Products include high-performance and radiation-hardened analog mixed-signal integrated circuits, FPGAs, SoCs and ASICs; power management products; timing and synchronization devices and precise time solutions, setting the world's standard for time; voice processing devices; RF solutions; discrete components; enterprise storage and communication solutions; security technologies and scalable anti-tamper products; Ethernet solutions; Power-over-Ethernet ICs and midspans; as well as custom design capabilities and services. Microsemi is headquartered in Aliso Viejo, California, and has approximately 4,800 employees globally. Learn more at www.microsemi.com.

Microsemi Headquarters

One Enterprise, Aliso Viejo, CA 92656 USA
Within USA: +1 (800) 713-4113 Outside USA: +1 (949) 380-6100 Fax:
+1 (949) 215-4996 Email: AVO-sales.support@microsemi.com
www.microsemi.com
MSC-F-0003 Rev 5

Do not distribute outside of Microsemi without permission.

Page 5 of 5