



Product Change Notification / SYST-05MORJ125

Date:

06-Jan-2021

Product Category:

Radiation Hardness

PCN Type:

Document Change

Notification Subject:

ERRATA - Rad-Hard 32-bit Arm® Cortex®-M7 Microcontroller for Aerospace Applications Errata Sheet

Affected CPNs:

[SYST-05MORJ125_Affected_CPN_01062021.pdf](#)

[SYST-05MORJ125_Affected_CPN_01062021.csv](#)

Notification Text:

SYST-05MORJ125

Microchip has released a new Product Documents for the Rad-Hard 32-bit Arm® Cortex®-M7 Microcontroller for Aerospace Applications Errata Sheet of devices. If you are using one of these devices please read the document located at [Rad-Hard 32-bit Arm® Cortex®-M7 Microcontroller for Aerospace Applications Errata Sheet](#).

Notification Status: Final

Description of Change:

- 1) Updated the Silicon Issue Summary table
- 2) Added new sections: Internal Slow RC Wrong Frequency and SUPC: Do Not Use PFD as Reset Source

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 06 Jan 2021

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

[Rad-Hard 32-bit Arm® Cortex®-M7 Microcontroller for Aerospace Applications Errata Sheet](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.