



Customer Change Requirement/Notification

保存部門 OS
保存期限 产生日期+1年

☐ Normal ☒ Urgency ☐ Requirement ☒ Notification

Part Number TM035KBH02

Topical TM035KBH02 driver IC change from NT39016D to NV3035.

Reason NT39016D will be EOL on 2014 Feb.

	Difference of Appearance	Difference of Function
Content	No machanical difference. No optical difference.	Customer must update LCD initial code and meet timing request of NV3035.

	Running Change Time	Packaging
Run	2014 Feb	No difference.

	Before Change	After Change
Attachment	The original driver IC is NT39016D. Customer's system must use NT39016D initial code and timing.	The new IC is NV3035. The initial code and timing is updated according to NV3035.
	This is only LCD driver IC change. No appearance different, no machanical difference, no optical difference. Customer must update LCD initial code and meet the timing request of NV3035.	

Reliability The reliability test of the module with IC NV3035 is pass.

Customer Approve Please customer advise how many samples are needed to do qualification.