



□CTSP Site:
No. 8, Keya Rd. 1, Daya Township, Central Taiwan
Science Park, Taichung County, 428, Taiwan, R.O.C.
TEL: 886-4 25218188

Date: 12/31/2025

Product EOL (End-of-Life) Notice

To Valued Customers,

This letter serves as the formal notification that Winbond is initiating the End of Life (EOL) for the DRAM products listed in the appendix.

Early placement of orders is encouraged because orders placed prior to the Last Order Date are subject to current inventory levels, which may vary upon market conditions and customer demand. Winbond reserves the right to limit Last Order quantity based upon capacity and material availability. Please notify Winbond local sales representatives as soon as possible if there are any concerns with this schedule below:

Notice Issue Date:	Dec 31, 2025
Last Order Date:	June 30, 2026
Last Shipment Date:	Dec 31, 2026

Thank you for your business and your understanding and continued support are greatly appreciated.

Sincerely,

Marketing Executive, CMS Marketing, Lim Teck Hwee
Winbond Electronics Corp.



□CTSP Site:
No. 8, Keya Rd. I, Daya Township, Central Taiwan
Science Park, Taichung County, 428, Taiwan, R.O.C.
TEL: 886-4 25218168

Appendix: List of EOL Product(s):

Affected Product	Recommended Replacement	Note
65nm 64Mb SDR/DDR	NA	

Affected Part Number	Recommended Replacement	Note
W9464*2J*	NA	
W9432*2J*	NA	
W9832*2J*	NA	
W9864*2J*	NA	

While the specifications are not exactly the same, we recommend replacing them with HyperRAM products for subsequent support. Further details can be discussed with our Marketing team.



□CTSP Site:
No. 8, Keya Rd. I, Daya Township, Central Taiwan
Science Park, Taichung County, 428, Taiwan, R.O.C.
TEL: 886-4 25218168

*Note: The scope of impact includes, but is not limited to, the items listed below.
However, due to certain products having not been shipped for an extended period or
being customized part numbers, and subject to system verification limitations and
other confidentiality agreements, some relevant items may not be fully listed.*

Affected Part Number
W9464M2JG-6
W983232JG-5
W986432JG-5
W986432JG-6
W9864G2JB-6I
W9864G2JH-6
W9864G2JH-6I
W9864G2JH-7
W9864M2JG-5
W9864M2JG-6