



Product End-of-Life Notification

EOL Number: HE084905

Date*: December 4, 2008

Product Description & Replacement:

EOL Part Number	Recommended Replacement Part Number
T555401-DBN	ATA5577M2
T555401-DDT	ATA5577M2
T555401N-DBN	ATA5577M2
T555401N-DBW	ATA5577M2
T555401N-DDW	ATA5577M2
T555402-DBN	ATA5577M2

There is no direct replacement.

ATA5577M2 is not a direct replacement but can be programmed to be functional compatible in the most common modes. Please contact marketing or your local sales office for details.

Reason for EOL:

Low demand

Last Time Buy Date: May 29, 2009

** All orders placed after the notification date are **non-cancellable** and **non-returnable (NCNR)**.*

Last Ship Date: November 30, 2009

Atmel Contact: pcnadm@atmel.com

Information provided herein is in connection with Atmel products and this information is provided "AS IS". Atmel assumes no responsibility for any errors that may appear in this document. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Atmel's Terms and Conditions of Sale for such products, Atmel assumes no liability whatsoever, and Atmel disclaims any express or implied warranty, including liability or warranties relating to fitness for a particular purpose, merchantability, or non-infringement of any patent, copyright or other intellectual property right. Atmel products are not intended for use in a product or system intended to support or sustain life which, if it fails, can be reasonably expected to result in significant personal injury. Atmel may make changes to specifications and product descriptions at any time, without notice.
