



Product discontinuance notification

Attention: INELTEK GMBH

Parts No.: IVFL-03\$

Issue date: 14th May, 2014.

Last order acceptance date: 30th June, 2014.

Reason for product discontinuance:

- ☐ Difficulty for getting related raw materials.
- ☒ No longer economical / viable
- ☒ Declining market
- ☐ Other:

Customer notification:

As a result of discontinuance reason(s) list above. Bolymin had decided to discontinue producing certain products and notify you through this product discontinuance notification.

Discontinuance date:

Product cannot be ordered beyond this date.

Confirmed by:

Name:

Signature:

Department / Title:

Date:

BOLYMIN Inc. 寶麗明股份有限公司

5F, No. 38, Keya Rd., Daya Dist., Central Taiwan Science Park, Taichung City, 42881, Taiwan.

Tel: +886-(0)4-25658689

Fax: +886-(0)4-25658698

www.bolymin.com.tw