



Product Change Notification / SYST-04LQCK978

Date:

08-Feb-2021

Product Category:

8-bit Microcontrollers

PCN Type:

Document Change

Notification Subject:

ERRATA - PIC16(L)F18855/18875 Family Silicon Errata and Data Sheet Clarification Document Revision

Affected CPNs:

[SYST-04LQCK978_Affected_CPN_02082021.pdf](#)

[SYST-04LQCK978_Affected_CPN_02082021.csv](#)

Notification Text:

SYST-04LQCK978

Microchip has released a new Product Documents for the PIC16(L)F18855/18875 Family Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at [PIC16\(L\)F18855/18875 Family Silicon Errata and Data Sheet Clarification](#).

Notification Status: Final

Description of Change:

- 1) Added Module 2.4 (ADC Offset Error).
- 2) Updated Master / Slave terminology to Host / Client.

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 08 Feb 2021

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

[PIC16\(L\)F18855/18875 Family Silicon Errata and Data Sheet Clarification](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.